	1	<u>^</u>		<u>٦</u>	1	г		(
A		2		3	4	5		6	
В									
C	OPTIN HP818	MILL-3D-CR-HARD 8	ENED						
D						(2.968)	60 <u>±</u> 1	120 120 ±0.70
E		M 50:1		\$6 h5	 	 			
F									
		REGRINDING INFO							
		TIP	0						
G	00	ter diameter	0						
		FLUTE	0						
	ADDING C)F WORKING LENGT	TH O						
	ADDING OF	WORKING DIAMET	fer O						
Н		DECOATING	0						
	•	YES OOPTIONAL ONO							
	1	2		3	4	5		6	

L 1 BLATT/MAP/S.A2 2 3 4 5 6

